
# SILOS & SITE HOUSE

Appin Road, between the parkway and St Johns Road, Bradbury Corrugated iron silos on road reserve





### HISTORY AND DESCRIPTION:

The house, now demolished, had early colonial characteristics and stood very closely to the alignment of Appin Road. The walls were of stone and brick, stuccoed, windows were small paned, the front door has sidelights, the verandah was stone flagged. It may have dated back to the 1820's.

#### CONDITION AND USE:

The new Appin Road alignment affected the house and was demolished in the 1970's. The Silos remain as a landmark.

#### HERITAGE SIGNIFICANCE:

- The site and silos have Historical significance as an early landmark.
- •

## HERITAGE LISTING:

**LOCAL:** LEP 2002

**STATE:** *Proudfoot:* Index No. 96, Category 2 *National Trust (NSW):* Demolished