

ATTACHMENT 2









LOCALITY PLAN




ATTACHMENT 3


Site plan




ATTACHMENT 4

Floor plans







STREET


MOORE

ALL ROOFGATES TO ROOF
 PROVIDE A RAINWATER TANK CAPABLE
 IN CAPACITY TO SAT ALL LEAK
 REQUIREMENTS THAT TO BE
 CONNECTED AS SPECIFIED IN BASK
 REPORT. PROVIDE OVERFLOW TO
 WASTEWATER SYSTEM.

PROVIDE A MONITORING AS PER
 SECTION

GROUND FLOOR PLAN

1:10




FIRST FLOOR PLAN


1:100




SECOND FLOOR PLAN
1:100



THIRD FLOOR PLAN
1:100




FOURTH FLOOR PLAN




FIFTH FLOOR PLAN
1:100

ATTACHMENT 5


Elevations




EAST ELEVATION
1:200



WEST ELEVATION
1:200






NORTH ELEVATION
1:200



SOUTH ELEVATION
1:200

ATTACHMENT 6

Shadow diagrams



ATTACHMENT 7

External finishes schedule



AS SEEN CORNER WARBY AND MOORE STREETS

NOTE : MATERIALS AND COLOURS ARE INDICATIVE ONLY, AND ACTUAL COLOURS MAY VARY DUE TO AVAILABILITY

EXTERNAL BRICK WALLS

FACE BRICK (BORAL) - LIMESTONE HUE



01

EXTERNAL FEATURE 01

PAINTED (DULUX) - GOLDEN ROD



02

EXTERNAL FEATURE 02

PAINTED (DULUX) - DEEP GARNET



03

EXTERNAL RENDER 01

PAINTED (DULUX) - LEXICON



04


EXTERNAL RENDER 02

PAINTED (DULUX) - VIVID WHITE



EXTERNAL RENDER 03

PAINTED (DULUX) - MISSOURI MUD



06

EXTERNAL RENDER 04

PAINTED (DULUX) - ITO



07

EXTERNAL RENDER 05


PAINTED (DULUX) - RAKU



08

WINDOW & DOOR FRAMES

ALUMINIUM - POWDERCOAT (DULUX) - MENSUS



09

PATHS AND DRIVEWAY

PAVER (BORAL) - PAVESTONE - CHARCOAL



10

GARAGE DOOR

PANELIFY (COLORBOND) - MONUMENT



11

PORCH FLOOR FINISH

PAVER (BORAL) - ABOOE - LINEN



12