
ATTACHMENT 1

Compliance with the ANZECC Guidelines at Council's water quality monitoring sites



ATTACHMENT 2

Site	Category
Simmo's Beach	Poor
Menangle Bridge, Nepean River	Poor

Classification of Recreational Water Environments (NHMRC 2008)